

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	1236	347/68.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 14:57			0
2	BRS	403	347/71.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:55			0
3	BRS	126	347/69.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:55			0
4	BRS	123	347/72.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:56			0
5	BRS	356	347/70.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:56			0
6	BRS	2059	(347/68 347/69 347/70 347/71 347/72).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 12:31			0
7	BRS	1457	"pressure buffer"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:58			0
8	BRS	0	((347/68 347/69 347/70 347/71 347/72).ccls.) and "pressure buffer"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 15:58			0
9	BRS	2126	pressure adj2 buffer	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 07:25			0
10	BRS	1	((347/68 347/69 347/70 347/71 347/72).ccls.) and (pressure adj2 buffer)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:00			0
11	BRS	9093	"air channel"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:00			0
12	BRS	7	((347/68 347/69 347/70 347/71 347/72).ccls.) and "air channel"	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:03			0
13	BRS	15118	buffer\$3 with pressure	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:03			0
14	BRS	10	((347/68 347/69 347/70 347/71 347/72).ccls.) and (buffer\$3 with pressure)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:16			0
15	BRS	39	((347/68 347/69 347/70 347/71 347/72).ccls.) and matsushita.as.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/07/31 16:17			0
16	BRS	10652	pressure with buffer	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 07:27			0

EAST BRS/Text Search ①

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
17	BRS	2059	(347/68 347/69 347/70 347/71 347/72).ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 07:27			0
18	BRS	9	(pressure with buffer) and ((347/68 347/69 347/70 347/71 347/72).ccls.)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 07:31			0
19	BRS	3212	(no?\$3eject\$3 dummy) with (channel chamber buffer)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:19			0
20	BRS	32	((347/68 347/69 347/70 347/71 347/72).ccls.) and ((no?\$3eject\$3 dummy) with (channel chamber buffer))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:20			0
21	BRS	3690	(no?\$3eject\$3 dummy) with (channel chamber buffer groove)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:24			0
22	BRS	34	((347/68 347/69 347/70 347/71 347/72).ccls.) and ((no?\$3eject\$3 dummy) with (channel chamber buffer groove))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:20			0
23	BRS	41452 7	(no?\$3eject\$3 dummy air elastic hollow) with (channel chamber buffer groove)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:25			0
24	BRS	305	((347/68 347/69 347/70 347/71 347/72).ccls.) and ((no?\$3eject\$3 dummy air elastic hollow) with (channel chamber buffer groove))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 08:26			0
25	BRS	8	("5023625" "5172141" "5594475").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 09:17			0
26	BRS	592	(347/68 347/69 347/70 347/71 347/72).ccls. and (color or (plural\$3 with head\$1))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 12:34			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
27	BRS	211	(347/68 347/69 347/70 347/71 347/72).ccls. and (color or (plural\$3 adj3 head\$1))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2001/08/01 13:53			0